





1.



2.



3.

Steel Process

1. Bending the steel piping
2. Mill out holes
3. Set up jig
4. Weld pieces together
5. Grind down welds



5.




4.

Wood Process

1. Build mold for birch plywood
2. Apply ammonia and glue
3. Ratchet plywood to mold
4. Cut plywood into shape
5. Drill holes and apply mineral oil then polyurethane



1.



2.



3.



4.



5.