



Planning and Fabrication Process



With a fully finished CAD model and final dimensions it was time to begin fabrication



After cutting the MDF to size, in the non weight bearing planes I cut out holes to save weight.

Using a special router bit I routed in a channel for T-molding edge banding to bring the design together.

