


Functions: Thermochromatic Technology

Okay



Inside temperature = 32- 40 degrees



Danger




Inside temperature = 41-140 degrees

A visual communication between the product and the user clearly shows us when the food has been left out too long and has spoiled.

Combines Basting with Marinating



Pour baste into top of handle



Basting



Push bulb on handle to apply baste

