

pected. At 1715 shifted berths.

October 3, 1944:

Anchored in Tinian Harbor. At 0632 underway to clear Harbor, due to heavy weather. At 0643 steering engine broke down, dropped starboard anchor. Anchored Tinian Harbor. At 1030, steering engine temporarily repaired, underway to cruise in the lee of Aguijan Island. At 1145 underway for Tanapag Harbor, Saipan. At 1417 anchored in inner Harbor Tanapag.

---

28 February 1945:

At 1310 - Held 3"/50 AA firing practice

At 1312 - Ceased firing - 3 rounds 3" expended - no casualties. M.V. BURNT ISLAND - three rounds 3" expended - no casualties; ATR 71 - three rounds 3" expended - no casualties; ATR 77 - one round 3" expended - no casualties; ATR 38 - three rounds 3" expended - no casualties; ATR 72 - three rounds 3" expended and 40 rounds of 20 MM expended - no casualties.

0800 position 15o45' North Latitude, 172o11' West Longitude

1200 " 15o45' North Latitude, 172o11' West Longitude

2000 " 15o45' North Latitude, 172o11' West Longitude