

# LASER THICK

Strong | Durable | Dependable

## INSTRUCTIONS

1. Unroll, cut to desired size, and remove the slip sheet.
2. Apply the laser mask to the side of the substrate that is to be laser ablated and blasted.
3. Squeegee out the air bubbles and wrinkles.
4. Remove the polyester carrier by flicking one edge of the carrier to loosen and then peel.
5. For porous substrates, such as unpolished brick and stone, anchor the laser mask by firmly pressing it to better adhere to the surface of the substrate.
6. Laser through the film to create your sandblastable mask.
7. Sandcarve to desired depth. Finish as desired.  
*Tip: After sandcarving, the laser mask can be left in place to serve as a stencil for paint filling. Once painted, the stencil is most easily removed within 15-45 minutes of applying paint.*

8. For removal of the film, simply peel.

P280 - Wear protective gloves/protective clothing/eye protection/face protection.  
P333+P313 - If skin irritation or rash occurs: Get medical advice/attention  
P305+P351+P338 - IF IN EYES: Rinse continuously with water for several minutes.  
Remove contact lenses, if present and easy to do. Continue rinsing.  
P501 - Dispose of content and/or container in accordance with local regional, national and/or international regulations.



USER'S GUIDE



MADE IN AMERICA &  
DISTRIBUTED GLOBALLY  
FOR OVER 65 YEARS