

“PATIENCE IS A VIRTUE”

POST-PRODUCTION CARE

\*AT THIS POINT THE TABLE EARNS ITS NAME.

DAMAGE DUE TO IMPROPER STORAGE AND MOVING RESULTED IN A NEED FOR MENDING AND ALTERATIONS.

ORIGINAL DESIGN DETAILS STILL REMAIN.

ASYMMETRIC CHANNEL ADDED TO TOP TO ACCOUNT FOR CORRECTED JOINERY.

