








PIMP MY SKETCH
Faster and furiouser




























① LIFTERS PUSH
IRON OFF CURVE.







② ROTATING
LIFTERS.




SHUTS OFF WHEN IT
SENSES FLESH...
INDUCTIVE.











CORD WRAP.




AUTOSORT
LAUNDRY.




SWIVEL?






COVER CHANGES .
RFID?
CORD MANAGEMENT ?



EXTRUSION .



WOOD HANDLES

