


GEAR HOUSING IDEATION



- ☐ Overheating
- ☐ Wheel Wear
- ☐ Cord Wear
- ☐ Many Tools at an Outlet
- ☐ Guard Adjustability
- ☐ Slider Switch Locks On
- ☐ Safety Switch
- ☐ Handle Cutting Position
- ☐ Handle Vibration
- ☐ RPM Identification
- ☐ Spanner Identification
- ☐ Lost Spanner Wrenches
- ☐ Kobalt VBL