Top user needs.

Main design drivers that need to be meet for a successful solution.



Transport and protect all devices and components



Manage hazardous waste and sharps



Maintain temperature requirements



Appropriate solution for both men and women